

KENDAL SKI CLUB RISK ASSESSMENT

AREA	Slope											CONTROL MEASURES								
ACTIVITY	Tow Operation																			
HAZARD	PERSONS EXPOSED TO RISK				WITHOUT CONTROLS								WITH CONTROLS							Acceptable Y/N
					OUTCOME				FREQUENCY				OUTCOME				FREQUENCY			
	Club Personnel	Skiers / Boarders	Visiting staff	Public	No Injury	Minor Injury	Major Injury	Fatality/Multiple Injuries	Highly Unlikely	Sometimes	Often		Inconvenience	Minor Injury	Major Injury	Fatality/Multiple	Highly Unlikely	Sometimes	Often	
Tow wire snapping	Y	Y				Y	Y		Y			Tow wire checked as part of maintenance routine. Issues to be reported during inspection and tow taken out of use.		Y	Y		Y			Y
Mis-operation of Tow	Y	Y				Y				Y		Slope supervisors / Instructors all trained in operation of tows. Slope checks carried out daily before tow use. Only tows operated by trained persons. Issues reported during inspection and tow taken out of use.		Y				Y		Y
Poma disconnecting from housing	Y	Y				Y			Y			Tow furniture checked as part of maintenance routine. Issues reported during inspection and tow taken out of use.		Y			Y			Y
Participant falling whilst on tow	Y	Y				Y	Y			Y		During use of tows during open/freestyle session, tow operation monitored by trained 'Slope Supervisors'. During Ski Lessons/Adaptive Sessions/Boarding Lessons tow operation monitored by trained 'Instructors'.		Y	Y			Y		Y